

Preliminary update - Mw7.8 Kaikoura Earthquake

(16-17 November 2015, supplement to 15 November update)

Upper Part of South Island

Contents

State Highway 1 – Heading North of Cheviot	2
Bridges.....	5
Landslips and Rockfall.....	8
Building Damage	12
Seddon.....	12
Hanmer Springs.....	12
Rotherham.....	13
Waiau	13
Cheviot.....	15
Waipara.....	16
Non-Structural Elements – Chimneys.....	16
Non-Structural Elements – Veneers.....	18
Other-Structural Damage	20

By Dmytro Dizhur and Marta Giaretton


ddiz001@aucklanduni.ac.nz

marta.giaretton@dicea.unipd.it

Preliminary update - Mw7.8 Kaikoura Earthquake (16-17 November 2015)

Upper Part of South Island

This is a preliminary set of notes from observations made on 16 -17 November 2016 with the route taken is shown below.



State Highway 1 – Heading North of Cheviot

- Road closed to public from Cheviot onward, professional and roadwork personnel allowed further with permission.
- 4WD access to get through the stretch of road from Cheviot onward. The roadwork teams started to fill some of the larger crevasses and levelling smaller slips.
- Going south to north, just before Peketa (-42.449696, 173.575200) is the furthest possible accessible point before one gets to a large rock fall. Machinery started to nibble through but didn't get very far. One of the first tunnels (-42.458537, 173.549893) has been cleared and is passible with caution.
- Large slips along most of the road stretch along SH1 heading north of Cheviot.
- Large number of landslides and rockfalls.
- Large number of GPS tagged photos collected. More photos at <http://www.egclearinghouse.org/2016-11-13-kaikoura/maps-and-photos/photo-gallery/>



Landslide into a creek below. State Highway 1, north of Leads Road



Movement of pavement due to land sliding below



Significant damage to the road pavement and movement of retaining structure



Significant damage to the road pavement



Major movement of a retaining wall



Significant damage to the road pavement and railing



Major bulging of the road pavement due to land slip above



Significant road pavement deformation near SH1



End of the road – Attempts are being made to start removing the rock fall
(-42.449696, 173.575200)

Bridges




Bridge along Inland Road, open for emergency heavy vehicles. Major damage to the bridge structure, all columns showing signs of plastic hinges (-42.634382, 173.066299)



Buckling of the bridge side railing due to deck movements



Breaking of the railing supports due to significant displacements of the deck structure



Loosening of connections



Significant differential movement of bridge girders



Hinging of bridge columns (see close-up)



Significant spalling at the base of column.
Longitudinal reinforcing bar buckling



Significant spalling at the base of column (southern column). Longitudinal reinforcing bar buckling



Major settlement of abutments, Oaro overbridge
#1790 (-42.512124, 173.506385)



Upto 1.0 meter of differential movement observed



Under bridge deck, visible hinging of the columns



Hinging at the top of column



Plastic hinging at the top of column



Signs of hinging at the column base



Signs of hinging at the column base



Lateral movement of the bridge abutment, not observed damage of the bridge structure
(-42.513496, 173.506657)



Historic steel bridge originally constructed in 1887. No observed damage, open to all traffic (SH7A leading to Hanmer Springs)
(-42.584195, 172.782635)



Movement of the Waiau River bridge #1842 deck and potential rotation of the pier (-42.655400, 173.033227)



Damage to the Waiau River bridge #1842 abutment (evidence of ground movement in the vicinity) (-42.655495, 173.031173)

Landslips and Rockfall



Cleared rock fall on SH70 towards Waiau



Land slide being cleared SH70 towards Waiau (by pass available)



Major rock fall on SH70



Example of typical rock fall on SH1, numerous cases along the stretch of road from Chevron to Kaikoura



Example of commonly observed landslides (photo taken along Leads Road)



Example of commonly observed initiation of ground spreading (photo taken along Leads Road)



Example of commonly observed along Leads Road




Major rock fall on Leads Road



Major slide along SH1



Major rockfall near coast along SH1, near miss of residential dwelling



Aerial view of the coastal SH1 showing location of subsequent photographs



(a) Major rock fall over SH1



Pre-earthquake (Google street view)




(b) Major rock fall over SH1 – attempts were been made to partially cleared



Pre-earthquake (Google street view)



(c) Damage to retaining structure and rock fall protection system



Pre-earthquake (Google street view)



(d) Blockage of tunnel entry due to rock fall, looking south



Rockfall over SH1, looking north



Commonly observed rock rolling path. Multiple examples along SH 70 towards Waiau



Typical example of soil sliding – blocking railway lines and tunnel entry



(e) Entry tunnel blocked due to rock fall, looking south

Building Damage

Seddon

- Damage to non-structural elements – veneer
- Damage to non-structural elements – masonry chimneys. Seems that most of the masonry chimneys have been previously removed (or lowered at roof line) in the past.
- Damage to non-structural elements – ceilings
- In-plane damage to RC with in-fill masonry buildings
- Historic masonry buildings: The entrance arch of the **Seddon War Memorial** (1926) is damaged



Seddon War Memorial (1926) – no visible damage



War Memorial entrance arch, significant damage

Hanmer Springs

- Damage to non-structural elements – masonry chimneys
- Historic masonry buildings: Significant damage to chimneys at the **Queen Mary Hospital** (1916). No damage to loadbearing masonry walls.



Queen Mary Hospital (1916) – Nurses' Hostel (no damage to loadbearing masonry)



Clay brick cavity masonry building - Queen Mary Hospital (1916) – Chisholm Ward (no damage)



Nurses' Hostel – Chimneys damage



Chimneys – large concrete chimney appears to be undamaged



Rotherham

- Limited damage to non-structural elements – masonry chimneys and veneers
- Historic buildings: Chimney collapse and observed crack-pattern in the **Watters Cob Cottage** (1880ca.), heavy damage at the column base and column-to-beam joints in the **Old Train Tower**.



Watters Cob Cottage – minor damage and collapse of chimney

Watters Cob Cottage, internal view



Old Train Tower

Hinging of the column-to-beam joints

Column base detail

Waiau

- Extensive damage to non-structural elements – masonry chimneys and veneers.
- Historic buildings: Chimney collapse and extensive damage on the **Cob Cottage museum** (1860, red tagged) while the timber **Presbyterian church** (1888) is green tagged. Heavy damage with tilting of the bell tower in the **All Saints Church** (1924, red tagged). Chimneys collapse and extensive crack-pattern in the **Waiau Lodge Hotel** (1910, red tagged).



Cob Cottage museum (earth structure)



Cob Cottage museum – evidence of textile reinforced mortars used as retrofit



Damage to the Cob Cottage museum



Presbyterian Church – timber framed building with no damage



All Saints Church, stone and lightly reinforced concrete



Tilting of the bell tower (note significant settlement of tower foundation)



Close-up of the significant bearing failure of tower foundation



Significant cracking of corners and gable wall



In-plane damage



Interior view



Waiau Lodge Hotel, vintage concrete structure



Horizontal cracking showing evidence of pier rocking




Cracking around widow openings



Partial collapse of chimney

Cheviot

- No visible damage was observed in the buildings (outside inspection only)
- Historic masonry building: **Knox Presbyterian Church** (1952), no visible damage was observed (external inspection only).



Knox Presbyterian Church, stone and concrete with no damage observed





Knox Presbyterian Church – rear view with no observed damage

Waipara

- Historic masonry building: **Glenmark St Paul's Church** (1906), diffuse earthquake damage that seems to be dated prior the 14/11/16 Kaikoura Earthquake (external inspection only).



Glenmark St Paul's Church – damaged also following the 2010/2011 Canterbury earthquakes



In-plane damage and gable end walls

Non-Structural Elements – Chimneys



Out-of-plane detachment of the chimney stack, Seddon



Example of removed chimney, Seddon



Example of removed chimney, Seddon



Horizontal crack at the chimney base and torsion, Hanmer Springs



Horizontal crack at the chimney base and sliding, Hanmer Springs




Extensive dislodgment of the bricks, Hanmer Springs



Dislodgment of the bricks,
Hanmer Springs



Collapse, Hanmer Springs



Local collapse of one of the
chimneys of a recent buildings,
Hanmer Springs



Non-damaged tall chimney,
Hanmer Springs



Non-damaged tall chimney,
Rotherham



Vertical crack-pattern, Waiau



Inward collapse, Waiau



Full collapse, Waiau




Collapse of the chimney stack,
Waiau



Waiau



Waiau



Oaro


Non-Structural Elements – Veneers



Out-of-plane collapse, Seddon



Close-up




Ties



Recently constructed veneer building, Seddon



Out-of-plane collapse



Ties



Detachment at the top of the veneer wall and initiation of out-of-plane collapse, Seddon



Dislodgement of the veneer blocks, Seddon




Torsion of the top part of the column, Seddon



Significant damage to veneer dwellings, Waiau



Heavy solid veneer cladding blocks



General lack of used ties



Corner damage and collapse of large veneer panels, Waiau



Collapse of large veneer panels, Waiau



In-plane and out-of-plane damage to veneer, Waiau




Collapse of moder brick veneer system, Waiau




Collapse of moder brick veneer and chimney, Waiau


Other-Structural Damage




Concrete blocks building, corner damage, Seddon



Dislodgement of the concrete blocks and close-up, Seddon



Concrete blocks building, corner damage, Seddon



Concrete blocks building, corner damage, Seddon



Concrete blocks building, out-of-plane collapse, Waiau



Concrete blocks building, extensive cracking and dislodgment of the blocks, Waiau