



Tuned mass damper

Parque Araucano building, Santiago





Building remained fully operational.

Only damage observed at roof level mechanical floor was electrical panel separated approximately 7 cm from wall



